

# GENERAL FIRE APPARATUS, INC.

MAIN WAREHOUSE | FABRICATION PLANT SERVICE CENTER | 4004 E. Trent Ave., Spokane, WA 99202  
P: (509) 535-4255 | F: (509) 534-8529 | TF: 1-800-541-4218 | www.generalfire.com



## SPOT LIGHT

### EXTREME DUTY TOW ASSEMBLY BY ROSENBAUER

**SPECIFICATION:** There shall be an extreme duty tow assembly installed at the rear of the unit. This unit shall be bolted to the chassis frame rails in four locations - one ahead of and one behind the rear spring mounts on each side. The tow assembly shall not be attached to the body. The two side frames shall be formed from plate steel and have a 3" flange on the lower portion. The crossmember shall be made from 3/4" plate steel bolted to the side frames and shall have a 4" hole in it for attaching tow ropes, etc. This extreme duty tow assembly shall prevent towing forces from being transmitted to the body.

